

To

The Principal,
Govt. Model Sanskriti Sr. Sec. School, Bikaner,
Distt. Rewari.-2522.

No. 9442

Dated 20/3/2024

**Subject: Regarding issue of building safety certificate GMSSSS, Bikaner.
(Rewari).**

Reference: Your office letter no.1177/24 dated 24.01.2024 & 1203/2024 date
05.03.2024

In this connection, it is intimated that the building of Govt. Model Sanskriti Sr. Secondary School Bikaner Distt. Rewari was inspected by the Sub Divisional Engineer, Provl. Sub Division No.I PWD B&R Rewari along with Junior Engineer concerned in the presence of Mrs. Nitu, PGT Hindi and reported that during visual inspection has been observed that the ground floor block "A" marked in violet colour in the drawing is in dilapidated condition. Roof slabs are of bricks arches with wooden planks. The wooden planks are eaten by mites, cracks have been developed in load bearing walls and seems to be constructed more than 50 years ago and recommended as condemn.

Three rooms along with varandah and varandha in front of two rooms as shown orange colour in the drawing require special repair. Other portion of the building seems to be safe condition.

Further, the safety certificate should not be used in legal and court case purposes.

DA/ Nil.

Executive Engineer,
Provl. Division PWD B&R Br.,
Rewari.

Endst. No.

Dated

20/3/2024 20/3/24

Copy of the above is forwarded to the Sub Divisional Engineer, Provl. Sub Division no.I, PWD B&R Br., Rewari for information w.r.t. his letter no.359 dated 13.03.2024.

DA/ Nil.

Executive Engineer,
Provl. Division PWD B&R Br.,
Rewari.